

"S. S. President-Gomez."

{ Ans. 8732.
Bot. 11771.
" 12272.

After completion it is stated that the propeller was fouled by a chain. Both screw shafts were drawn and dressed up.

It is submitted that this vessel is eligible for
THE RECORD.

F. L. M. C. - 4.22.

Fitted for Oil Fuel, 3.22., F.P. above 150° F.
Both S. - 4.22.

Ans. L.F.
11/5/22.

It is concluded that forced draught is fitted, but this should be confirmed by the Amsterdam Surveyors.

In Ans. 12.5.22

Lloyd's Register
Foundation

W1298-0138