

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

When handed in at Local Office

Port of

London

No. in
Reg. Book.

Survey held at

Date, First Survey

Last Survey

19

2807

on the Wood, Iron or Steel

"Kokuryu Maru"

(No. of Visits)

TONNAGE:-

Built at

Innoshima

By whom

Osaka Iron Works, Ltd.

YEAR.

MONTH.

GROSS

6113

Owners

Dairen Kusen K.K.

Owners' Address

When 1921

8

UNDER DEK.

5180

Managers

Port belonging to

Dairen

NET

4459

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Last Report, No.

10392

Port

Kob

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:-

Shell Plates.

Frames.

R. Frames.

Floors and Bracket Floors

Beams.

Inner Bottom Plates.

Dk. Plates.

Other Items:-

Renewed

Removed and Paired or Repaired

Paired or Repaired in place

PRESENT CONDITION OF THE

Plating of Decks

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined and found efficient?

Air and Sounding Pipes

Dblng. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treenails

Breasthooks & Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at openings

Ditto Ditto at other places

Stringers, Clamps & Shelves

Salting

Copper, or Y.M. of Wood Vessels

(State if on felt.)

When put on, Month

Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Chain Locker

Cables (State if now ranged)

length mean diamr.

(on board)

Rule length size

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24.

Survey Fee (per Section 29)

Fees applied for,

Special Damage or Repair Fee (if any)

Received by me,

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Committee's Minute

TUE. 4 JAN 1938

Character Assigned

Withdrawn

W.D. Bujoon Maru insert

General Committee

Thursday, 6th January, 1938.

Classing Committee

decision confirmed

Lloyd's Register Foundation