



LLOYD'S REGISTER OF SHIPPING

MEIKAI BUILDING

No. 32, AKASHI MACHI,

KOBE, 25th October, 1929.

TELEGRAMS: "REGISTER" KOBE

TELEPHONE: 2530 SANNOMIYA

The Secretary,
LONDON.



Dear Sir,

With respect to the 1st Entry reports on the M/V "KONSAN MARU" (Mitsui Bussan Kaisha No.161) now forwarded under separate cover I beg to inform you that this vessel has been in service since the beginning of September last but before she left Builders Yard it was pointed out to them that the bilge pumping arrangements in the Motor Room were not in accordance with the requirements of the Rules, as only one 3½" dia. Centre Scupper ~~was~~ arranged for draining the Motor Room into the Motor Room bilge well. After some discussion it was decided to fit a 6" scupper both port and starboard and replace the centre 3½" dia. scupper by one 6" dia. (See plan approved 4/10/29).

It was originally intended to carry out these alterations within a few days and the reports and provisional certificates were held back pending completion of this work.



© 2021
Lloyd's Register
Foundation

W1310-0207 1/2

CONFIRMATION OF LETTER

(2)

LLOYD'S REGISTER OF SHIPPING

MARKET BUILDING

NO. 32, AKASHI MACHI

The owners have now requested that these alterations be postponed until she returns to the Builders Yard about March 1930 as she is urgently required until then and I understand the manhole cover (near the centre scupper) leading from the tank top to the Motor Room bilge well will be left off in the mean-time.

I am, Dear Sir,

Yours faithfully,

Clive Bell

RECEIVED

Chief Engineer, Brinsford
Delivered to the Chief Ship Engineer



© 2021

Lloyd's Register
Foundation

0207 2/2

Referred to the Chief Ship Surveyor,
and the Chief Engineer Surveyor.

[Handwritten signature]

11 NOV 1929

10

W. E. [unclear]

Yours respectfully,

I am, Dear Sir,

I am sorry to hear that you have had some trouble with the engine. I am sure that the engine is not the cause of the trouble. I am sure that the trouble is due to the fact that the engine is not properly adjusted. I am sure that the trouble is due to the fact that the engine is not properly adjusted. I am sure that the trouble is due to the fact that the engine is not properly adjusted.

(S)



© 2021

Lloyd's Register
Foundation

