

If the Vessel has
the tanks examined
etc, and of the ins
ast Report

W1315-0063

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

30th July, 1937.

Dear Sirs,

With reference to the classification in the Society's Register Book of the steamer "ANGLO", I beg to acquaint you that the Committee have today had before them a report received from the Society's Surveyor at Bergen, from which it appears that this vessel has been placed in dry dock and the greater part of the Third Special Survey No.2 carried out.

The Surveyor reports that repairs on account of wear and tear are required in connection with the Special Survey, and in view of the extensive nature of these repairs it is recommended that the Survey be completed at an early date, and I shall be glad to learn that you will be good enough to make arrangements accordingly.

I have to add that it is further recommended that the starboard bilge pump casing, which was temporarily repaired, and the H.P.Cylinder liner be renewed before the end of January, 1938; also that the tunnel bearings (except aftermost and No.3 from aft) be specially examined before the end of January next, and that the starboard furnace of the starboard boiler be specially examined before the end of June, 1938.

I am, Dear Sirs,
Yours faithfully,

Mrs. Valdemar Skogland, A/S,
HAUGESUND,
Norway.

2021
L
Refer to the
Classification Committee.

Lloyd's Register
Foundation