

Less Engine Room 112-61
Less Navigation Spaces 9-19

Long Bridge Deck }
Beam at side to top of keel }

Port belonging to Bristol

5c,8,11.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No. 2489

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

Depth "d"

Framing: Table No.

Description

Longitudinal No.

Proportions

Length
Depth =

Deck Sheerstrake

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed \pm 100A.1. (Class) 'Steam Trawler' as recommended.

\pm 100A.1. (Class) 'Steam Trawler'

1 Dr

BK 75 3 B.H. Gen Lloyd's at 60 269

Tee Bulb, or Channel }
Angles on upper edge }
Spacing }
BEAMS, Bridge Deck, Angle, Bulb Angle, Plate, }

Angle on ditto }
Tie Plates }
Deck. Material and thickness }
Forecastle Deck Stringer Plate }
h'dth & th'kns }