

REPORT of SURVEY for REPAIRS, &c.

20 DEC 1937

Date of writing Report 19... When handed in at Local Office 19... Port of London

Name of Ship Survey held at Date, First Survey Last Survey 19

Reg. Book. 35241 on the Wood, Iron or Steel Toho Maru

TONNAGE:— Built at Port Glasgow By whom Russell & Co When 1918 YEAR. MONTH.

GROSS 4717 Owners Laura Hosi N.K. Owners' Address (if not already recorded in Appendix to Register Book).

UNDER DK 4266 Managers Port belonging to Laura

NET 2930 Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CelD BorDBa feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity tons. FPT tons; APT tons; MT feet tons. Last Report, No. 9878 Port Kob

CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned now expired. Machinery and Boiler Surveys (including date of N.B. in any).
+100A1
12.36
+LMC 12.36
CL 12.36
H.D.M. No 3-730
H.K.B. No 1-34

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE			
Deck	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Vell.) When put on, Month Year.
Caulking of Decks	State if Tanks now tested	Dbng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length (on board) mean diamr.
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stems ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Shelves ditto	
		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

Survey Fee (per Section 29)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute / TUE. 4 JAN 1938
Character Assigned Withdraw class & insert
Surveyor to Lloyd's Register of Shipping.
General Committee
Thursday 6th January 1938
Classing Committee
decision confirmed

Has a Survey also been held on the Machinery of the Ship? If so, is the Report sent now, or when will it be sent?

Is certificate required? If so, to be sent to

W1320-0245

10m, 737—Transfer Ink. The Surveys are requested not to write on or below the space for Committee's Minutes.