

with *yes* If fuses are fitted on main switch board to the cables of main circuit *yes* and on each auxiliary switch board to  
circuits *yes* and at each position where a cable is branched or reduced in size *yes* and to each lamp

ds 5-6-2

eller 28-6-

1-10-2

10-20

9-20

Do. LLOYD 18-11-19  
Do. LLOYD 11-11-19  
Y.J.B.

SS. "Seikai Maru"

Kob. Rpt 3051.

The Surveyors' General Remarks & Recommendations have been omitted from the report but the machinery appears to be a duplicate of that fitted in the SS "Genzan Maru" built by the Osaka Iron Works in 1918.

~~The particulars of boilers~~

It is concluded that the machinery has been fitted in accordance with the Rules & that the workmanship & materials are good. but the Surveyors should be requested to forward their general remarks & recommendations

It is submitted that  
this vessel is eligible for  
THE RECORD. + L MC. 11.20 FJ

Rel  
23/2/21

AR R

© 2021

Lloyd's Register  
Foundation

owns in cables, now made, insulated, and protected mechanical joints, protected with water  
iron boxes & insulated by porcelain or slate bases.