

W134-0092

Chief Surveyors

Received from Chief Surveyors

SHIP'S NAME

WELLFIELD

Report

N. Yk

No. 41120

For the CHIEF SHIP SURVEYOR and CHIEF-ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/2.)

2nd No. 1 SURVEY PARTLY HELD.

8.40

When proposed to be completed not stated

of Survey held, &c., except that the bunkers require to be examined and tested.

Subject to No. 6 plate from aft in 3rd strake below sheer (p.s) E.W. 11.39 being examined at the next dry docking.

(15 fathoms of chain cable requires to be supplied).



© 2019

WAS
24.7.41

Lloyd's Register

The Surveyors should be informed it is concluded that the cofferdams have been tested, the pump rooms and structure in way of strums examined, the rigging repairs effected as recommended and that the diameters of chain cable as reported are in error, but they should confirm.

W. L. R. 40

length