

REPORT OF SURVEY FOR REPAIRS, &c.

(Received at London Office 27 6 39) **DISCLOSED** / **RAY No. 201** No. 107551a

Date of writing Report 10 When handed in at Local Office 10 Port of London

No. in Reg. Book Survey held at Date, First Survey Last Survey 19

81564 on the Wood, Iron or Steel *Iron* "TAMON MARU" (No. of Visits)

Tonnage: GROSS 8134 Built at Tsurumi By whom Chano S.B.C. Ltd. YEAR 1919 MONTH 5

UNDER DEK 7732 Owners Hatuma Kisen K.K. Owners' Address Managers Yamashita Kisen K.K. Port belonging to Hufju

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor DBa feet; uE&B feet; f Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

total capacity tons. FPT tons; APT tons; MT feet tons. N.B.—All alterations in the existing records should be underlined.

Last Report, No. 10609 Port *Kob*

CHARACTER: * for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of N.B., if any).
 + 100 AI Shelter dk with foreboard 4.38 + 1mc 4.38 CL 2.36
 ss Kob 16 3-3, 33 ss Yka 16 1-37.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting (State if examined.)	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38"

Survey Fee (per section 29)	£	Fees applied for,	£
Special Damage or Repair Fee (if any) (per Sec. 29)	£	Received by me,	£
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute
 Character Assigned *Mildredan class*
While onms 2 used (6.7.29)
Kob (Code)
Rb

Surveyor to Lloyd's Register of Shipping.
 Confirmed by General Committee
 Thursday, 6th July, 1939

Lloyd's Register Foundation
 W1341-0035

The Surveyors are requested not to write on or over this form.

This certificate requires to be sent to