

Subject to permanent repairs being effected to keep the
 plating on port & starboard sides at Onn's convenience
 MTL 4687. (6/38)

3m, 9.37.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Anneliese Essberger*

Rpt. *Rot*

no else? If

of the Chief Ship Surveyor are desired on this case for the consideration of the

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or circumstances giving out clearly any exceptional features in connection with the case, so that the Classing Committee may be presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

for

Condition

Rotterdam

The

Surveyors report this vessel

dry dock, bottom cleaned and coated, ~~repairs to~~

~~and minor repairs effected.~~ The shell plating as above examined and found satisfactory. The Onn's representative states that this will be dealt with when the vessel undergoes special survey at the end of this year at which time also fracture in the tank will be dealt with. The surveyors recommend


It is submitted the vessel appears worthy to remain as is.

Classed with ^{out} record of survey subject as recommended and as amended.

As now. Subject, etc

Amend. S.R.L.

W1349-0177



© 2021 Lloyd's Register Foundation

not
 Sounding Pipes
 Lights
 en's, Lids, &c
 always
 of Wood Vessels
 ditto
 ditto
 ditto

Reverse Frames	cient? <i>not end</i>	Treenails	ditto
Longitudinals	Have Sluice Valves now been examined and found	Breasthooks & Stemson	ditto