

WED. 3 OCT. 1923

No. 20868.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 1st Oct. 1923. When handed in at Local Office 2 Oct. 1923. Port of NEWPORT, MON.

No. in Survey held at NEWPORT, MON. Date, First Survey 11th Sept. Last Survey 26th Sept. 1923.

Reg. Book. on the Wood, Iron or Steel s.s. "CYNTHIANA" (No. of Visits) 10 Master

TONNAGE:- Built at Chepstow By whom Monmouth S.B. Co. Ltd. When (See below)

GROSS 3443 Owners Harris Dixon Ltd. Port belonging to

UNDER DEK 2851 Owners' Address

NET 1984 (if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock CH. Bailey & Co. Ltd. Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Secretary's Letter D. painted on Ship and now verified 3 ft. 8 1/2 ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Special General Examination, as per Secretary's Letters.

Now done: Vessel placed in Dry Dock: bottom and rudder cleaned, examined & recoated.

Hold, coal-bunkers, oil-fuel bunker, engine and boiler space, pump-rooms, fore and after

peaks, cargo-tanks, expansion tanks, decks and deck erections, hatchways, covers and

supports, casings, masts rigging, ventilator coamings, general equipment, boats,

anchors, chain-bolter, steering-engine (externally) rods, etc., windlass (externally), & all

double-bottom & peak tanks (internally) examined & found in good order. Freeboard verified.

At the request of the Owners all cargo tanks and cofferdam have now been tested under pressure

and found, or now placed, in good order.

From the above examination, the undersigned Surveyor hereby certifies that no material

deterioration has taken place with regard to the hull & equipment (including boats) of the P.T.O.

SUMMARY OF DAMAGE REPAIRS:-

Renewed ... Plates. Frames. R. Frames. Floors. Beams. Str. Plates. Dk. Plates. Other Items:-

Removed and Fair'd or Repaired ...

Fair'd or Repaired in place ...

PRESENT CONDITION OF THE

Decks Good

Caulking of Decks " State if Tanks have been examined inside Yes.

Waterways " State if Tanks now tested Cargo tanks only.

Coamings " Bulkheads Good

Beams & Fastenings " Ceiling " Good

Outside Plating " Cement or Asphalt (Cement) " Good

Caulking of ditto " Rudder " Good

Rivets " Steering gear and its connections " Good

Breasthooks & Crutches " Windlass " Good

Transoms " Have Pumps now been examined and found efficient? No

Frames " Have Sluice Valves now been examined and found efficient? Yes.

Reverse Frames " Have Watertight Doors now been examined and found efficient? Yes.

Floors " Have Ventilators and their Coamings been examined and found efficient? Yes.

Keelsons " Stringers " Good

Stringers " Inner Bottom Plating " Good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel is in good condition, and, in the opinion of the undersigned, eligible to have

Date of build of 9,23, as per Secretary's letter (D) of 21st Aug. 1923.

Survey Fee (per Section 20) Special Exam. 15: 15: Fees applied for, 10:

Special Damage or Repair Fee (if any) (per Sec. 20) 2: 2: Received by me, ST. Bryden.

Travelling Expenses (if chargeable) (per Sec. 20) 2: 2: TUE OCT. 9 1923 Surveyor to Lloyd's Register of Shipping.

Bond Surveyor's Fee (if any) FRI. OCT. 12 1923

Committee's Minute See J.E. App. 10001

Character Assigned Rpt. 20852 Carrying Petroleum in Bulk

This Certificate required by If so, to be sent to

17358-0021

87. B.

87B.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Lloyd's Register
Foundation