

12 MAY 1939

1

by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"Irmitant Cords"

Rpt. Cpn.

No. 10880

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Order of Survey

DAMAGE.

Damage through heavy weather, contact with quay & grounding.

How repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	3						
Moved and faired or repaired.....	7						
Faired or repaired in place.....	18						

Other items:-

Vessel examined on a pontoon, bottom cleaned & coated
repairs effected to decks doubling & hatch corner angles.

When submitted the vessel is worthy to remain as classed with

Order of Survey 4.39.

100A1.

With feed.

4.39 Cpn.



© 2020

Lloyd's Register
Foundation

W1360-0148