

5 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Woodsdrecht

Rpt.

Rel.

No. 13244

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

Bombs DAMAGE & WEAR AND TEAR.

(2nd No 1 due 11.45)

Damage. Red plates of 2 dynamos repaired.
Wear & tear The propeller & all main cylinder liners renewed
 & minor repairs.

It is submitted the vessel is eligible to remain as classed with
 record of Survey till Dec 52 as recommended. 54.42.
 241.

Subject to the head plate of the Dynamo oil engine being
 examined before the end of 543.

on 639.

See also entries of 9/6/42 re pump room lighting

VR37-0147