

damage through stress of weather, and the Surveyor recommends

ce

be

ting

ESQUIMALT. — *Malta*, May 5. — Auxiliary vessel *Esquimalt*: Surveyor reports damage hull slight without affecting seaworthiness. Master insists seven new sails, including spare, necessary for safe navigation, propelling machinery defective. Sails cannot be supplied locally, dockyard owing pressure work can supply only one sail, therefore towage necessary.—Lloyd's Agent per *Salvage Association*.

A

A

A

A

A

be

per Lloyd's List 7/5/19

Lloyd's Register
Foundation

as

W1382-0073