

20 SEP 1917

Wood Auxiliary Twin Screw Schooner "ESQUIMALT".

Seattle Report No.520.

The scantlings and arrangements are as approved and the vessel has been salted, and the material specially treated by the carbolineum process as approved by the Committee for two additional years, subject to Special Survey at periods of 4 & 8 years from the date of completion.

It is submitted the vessel appears worthy to be classeed 12.A.1, as follows, viz:-

9 years Table A.

1 year for salting

2 years for special carbolineum treatment)

Subject &c.

12 A.1.

"Salted & specially treated."

Lloyd's A & C.P.

"Pt. G.I.B".

"Hard Wood Treennails"

M. A. P.
19. 9. 17.

The Surveyors should forward all approved plans with the report of the last vessel of the series building.



© 2021

Lloyd's Register Foundation

W1382-0082

PLANKING INSIDE.—The Limber-strakes and Bilge-strakes are of Douglas Fir

The Ceiling, Lower Hold, and between Decks of Douglas Fir

FASTENINGS.—To Hold Beams

Shelf Pieces and Clamps of Douglas Fir