

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report When handed in at Local Office 19..... Port of London

No. in Reg. Book. 924 Survey held at on the Wood, Iron or Steel Pad 5 - Boydell Date, First Survey Last Survey (No. of Visits) Master

TONNAGE: - Built at London By whom Thames Iron Works, L.B. & C. 1905 - 5 YEAR. MONTHS

GROSS 126 Owners Royal Serbian Powdered S.S. Co. Port belonging to ✓

Net 58 Owners' Address (if not already recorded in Appendix to Register Book).

Afloat or in Dry Dock? Name of Dock Destined Voyage
LDBorDBa feet; uE&B feet; f feet; }
acity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

essel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, of the inner bottom plating, especially in the boiler space.

Report, No. 69693 Port Lon

urveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the pairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; being detailed in the body of the report, should be summarised in the form shown below. Whenever the of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on this form. State also the dates and initials of any letters respecting this case.

ases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were
Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

(Handwritten notes)
\$ (Paddle)
Serbia
8.09 (m)

DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
and Faired or Repaired								
Repaired in place								

CONDITION OF THE	Stringers	Dbing. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)	When put on, Month Year
State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.		Boats
State if Tanks now tested	Scuppers		Masts, Yards, &c.
Bulkheads	Cargo Hatchways		Condition, how ascertained
Ceiling	Hatches		(State if wedges removed)
Cement or Asphalt (state which.)	Planking of Wood Vessels		Sails
Rudder	Caulking ditto		Equipment letter
Steering gear and its connections	Treenails ditto		Anchors, No. of
Windlass	Breasthooks & Stemson ditto		Cables (state if now ranged)
Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto		length (on board) size
Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto		Rule length (per Table 22) size
Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto		Hawser & Warps
	Stringers, Clamps & Shelves ditto		Standing & Running Rigging
	Salting ditto (state if examined.)		

Observations, Opinion as to Class, Recommendation, &c. :—
ate clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon ey, thus for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of ,09," or "to remain as classed and to have record of survey, 1,09, and the notations of ss No. 1-09 and pND09, &c."

Section 28)	£	Fees applied for,	19.....
or Repair Fee (if any)	£	Received by me,	19.....
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Surveyor to Lloyd's Register of British & Foreign Shipping.
 General Committee,
 Thursday 19th August 1909
 Classing Committee
 decision confirmed

Committee's Minute TUES. 17 AUG 1909
 Character Assigned Withdrawn Class + insert
 Write down on 19/8/09

100 (The Surveyors are requested to be sent to W 1393-0116)