

1

Sent to Chief Surveyors

VESSEL'S NAME STEEL S.S. "BUFFALO BRIDGE" Report N.Yk No. 17517

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/23.)

Date of Survey

When due

Kosei Maru
T(PR)-U.S.A.
discovered - No L.

The Dainton Pump has been dispensed with for the present.
Steel and 4 Anchors listed by the American Bureau Surveyors.

* 100 A-1 (steel)

10k (steel) 2nd tier beams in fore & after holds & webframes.

Cell DB 251' 327 t. MT 20' 394 t. FPT 111 t. APT 69 t.

FK. 6 BH. pt. am. CP. P30', B90', F35'.

It is concluded, the Stem Post, Rudder & Propeller Posts are as approved, but the Surveyors should be requested to state if this is so.

Deck, Single Angle, Bulb,
Angle, Plate, Toe Bulb, or Channel

Spacing

BEAMS, Third and Fourth Deck, Single Angle,

Bulb, Angle, Plate, Toe Bulb, or Channel

24" and 54" ✓ and 54" ✓

Poop Deck Stringer Plate, breadth & thickness

Angle on ditto

DISCLOSED
SECTION.

No. 17

M at 3
11-11-19

© 2021

Lloyd's Register
Foundation

V1402-0054

60