

Ship Surveyor 2.6.14

Received from Chief Ship Surveyor _____

Steel $\frac{7}{8}$ " Coronal "

Rpt. Lts

No. 760

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

orsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
g out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
ted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st ss. No 1 for Reclassification

The class of this vessel was expunged from the
r Book with a Red Line in January last on account of the
shaft not having been drawn.

The Surveyor appointed by Lloyd's Agents at Para
reported that the screw shaft had been drawn and the vessel
generally.

It is submitted the vessel's class be re-instated
register Book with record of survey 3.14, ~~and notation~~
~~a. No. 2.14.~~

22.6.14


14 Pra

~~22.6.14~~

22.6.14

[Signature]

8.6.14.



© 2021

Lloyd's Register

W1415-0136