

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office - 1 SEP 1925)

Date of writing Report 28-8-1925 When handed in at Local Office 29-8-1925 Port of Leith

No. in Survey held at Leith Date, First Survey and Last Survey 22-8-1925 (No. of Visits One)

7908 on the Machinery of the Wood, Iron or Steel Twin Sc. "ATHELCHIEF"

Package Gross Vessel built at Dundee By whom Baledon, S.B. & Co. Ltd. When 1925

Net Engines made at Greenock. By whom J. G. Kincaid & Co. Ltd. When 1925

Boilers, when made (Main) (Donkey)

Owners Athel Line Owners' Address (if not already recorded in Appendix to Register Book) Port Liverpool Voyage Java.

Managers British Molasses Co. Ltd. If Surveyed Afloat or in Dry Dock Imperial (Dry) Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Donkey Boilers

First Report No. Port

Particulars of Examination and Repairs (if any) Docking

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Is a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

Was this not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? no. Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted new? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

What is the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? Fit

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete.

Propellers & fastenings, sea coast connections & stern bushes examined found satisfactory.

General Observations, Opinion, and Recommendation:—The machinery of this vessel (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 2, 11, B.&M.S. 2, 11, or S.L.M.C. 2, 11, 140 lb., F.B., &c.) now in a safe working condition & eligible to remain as class contemplated.

Fees applied for 19 Received by me, 19

Committee's Minute signed See Gen SE 8538

Is a Certificate required? If so, to be sent to

Lloyd's Register Foundation W 145-0142

To be attached to the First
Entry report.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

JWR.
1/9/25.



© 2020

Lloyd's Register
Foundation

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.