

It is submitted the New York Surveyors should be requested to state whether the screw shaft of this vessel is fitted with a continuous liner and, if not, whether the joints have been burned as required by the Rules.

These particulars are not stated in the report.



*AWD* © 2021

*17/7/18*

Lloyd's Register  
Foundation

W1462-0033