

F.E.

50,18.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

St J. Benwood

Rpt.

Mar

No.

6081

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Budg. Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	✓	✓
Description of Framing:—Bulb angle, as approved. (viz., ordinary, deep, zed, channel or bulb-angle).		

The Steam pipe is 4 1/4" in circumference as per the approved midship section.

In this repair. This vessel appears to have been built in accordance with the new Rules and the approved plans, and it is submitted she is eligible to be classed + 100A1 (Steel) as recommended.

+ 100A1 (Steel)
1st (Std)

W.B. Bu D B a 111 n 843 38 f 147 10766 F.P.T 1496 APT 986
FR. 6BH. Elm. Lloyd 986P PHH B10H F 31

© 2021
Lloyd's Register
Foundation
x148-0005

PILLARS, In 'tween Deck, size and spacing

"

Hold

Quarter 'tween Dks.

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

"

Angle on ditto.

Tie Plates