

Adm: Drifter "Mountain"

It is concluded that a set of coupling bolts have been placed on board, but as this is not stated in their report, it is submitted the Hull Surveyors be requested to state if this is so

done by 10/6/20

AWD

10/6/20

10/6/20

W1484-0020

GRS

Lloyd's Register Foundation