

What special means, in the absence of internal examination, were adopted by the surveyor to assure himself of the thorough efficiency of these parts of each Boiler?

To what pressure were they afterwards adjusted?

Mr. [unclear] concluded the Condenser has also been examined at this time but the Auckland Surveyor should be requested to confirm this.

Auckland 465

T. J. [unclear]
20.3.14

Lloyd's Register
Foundation

W1487-0134