

Received 11th June, 1914.

Answered _____

Extract from letter dated 6th May, 1914, received from _____

The Society's Surveyor at AUCKLAND, N.Z.

Original letter with _____

Vessel's Name "KARORI".

In reply to your favour of the 31st March, I examined the plating under the side lights. This had never been cased in or lined, consequently depreciation was not more than in other parts of the hull, and as the plating in the way of the side lights had been kept well scaled and painted, I did not consider it necessary to drill the plating here or at any part. I regret the omission to specially mention these matters in my report, but trust this explanation will be accepted.

Notes
M
12/6/14



© 2019

Lloyd's Register
Foundation

W1487-0174