

Less Crew Space
Less above Crew

12.15.

Report to Chief Surveyors 14.6.17 Received from Chief Surveyors
VESSEL'S NAME Sheels Benjamin Brewster Report Phl No. 2566

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey _____ When due _____

❖ 100A-1 (Steel) carrying petroleum in bulk.
2 DKS. (Steel) + Webframes. Longitudinal framing
Cell DB u E + B 67 u Bunkers 13 2456. D.T + 32. 3366. F.P.T. 106. G.P.T. 1056
F.K. 18 BH (14 BH 6 u 4 BH 6 2" x), acc. pl. Cam.
P 114. B 29' F 41. Inly aft

M
15.6.17

It is ^{understood} ~~concluded~~ the tank top in boiler room is .56 thick as required ^{but} the surveyor should state if this is so. *Y*

M



© 2020
Lloyd's Register
Foundation
WISO-0072

BEAMS, Thi
B