

Doni P.P. Marmora


The Surveyor should be requested to state whether
the Screw Shafts are fitted with continuous liners

Em.S.

24.10.03.

M.S.

24.11.03



© 2021

Lloyd's Register
Foundation

W1523-0088

pressure by rules 236 Superheater or Steam chest, now connected to boiler