

CONFIRMATION OF LETTER.

12064 "SIRIUS". Deferred for a properly fitted watertight door controlled from the deck to be fitted for access to the cross bunker as usual and as fitted on the opposite side of the vessel, and also for cargo battens to be fitted in the vessel as required by the Rules unless she is to be exclusively engaged in the carrying of coal, ore or wood.

I have to request that you will state whether the angles to the margin plate and outside plating in the ship are $3\frac{1}{2} \times 3\frac{1}{2} \times 9/20$ " as shown on the midship section or $3\frac{1}{2} \times 3\frac{1}{2} \times 8/20$ " as stated in your report.

P.T.O.



© 2021

Lloyd's Register
Foundation

W1525-0172 1/2

COPY.

Q. n. k.
As the vessel has been fitted with cargo battens as required by the Rules, reference should have been made to this matter in your recommendation as to the vessel's Class, and the body of your report should have contained a statement with reference to the question of the watertight door.

I have to request that you will return the sketch of "the moveable" door in the stokehold bulkhead.



© 2021

Lloyd's Register
Foundation

W1525-0172 1/2

W1525-0173 1/2