

for 6. 10. 14.

Received from Chief Ship Surveyor

1st No. 2. SURVEY FURTHER ADVANCED.

Ship S. S. "Manipur"

Rpt. Gal

No. 3327

Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to state any exceptional features in connection with the case, so that the Classing Committee may have all the salient points for their consideration. (Extract from Sub-Committee's Report, 24/5/92.)

this vessel is subject to the rudder frame, repaired by oxy-acetylene gas in Nov: 1912, being specially examined at next dry docking.

S. No. 2. due 1. 14. partly held at Glasgow & Liverpool.

advanced as follows:- and to complete same.

tanks, the angle attachments of floors & tank top to be and repaired under the hold pillars (particularly under those in the Square of the hatch.

ing repairs effected due to wear and tear:-



posed to complete the survey not stated

mitted this proposal might be approved and the vessel be

tain as classed. Record of Survey, & notation of

2 being deferred until completion of same.

E. B. ...

M. ...

P.S.
6. 10. 14.

remains to be done to complete the

S.S. No. 2



© 2021

Lloyd's Register Foundation