

Chief Ship Surveyor

19/12/11

Received from Chief Ship Surveyor

NAME

St. G. Mallina

Rpt.

Bsk

No.

374<sup>a</sup>

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Damage

This vessel has been examined in dry dock, as recommended by the Brisbane Surveyor in May last, after grounding, and the bottom has been cleaned and coated.

The vessel retains her class, subject to some damage sustained through striking a wharf being made good at the first available opportunity.

It should be observed that the classification of this Company's Steamers is not maintained in the Society's Register.

It is submitted action might be deferred.



© 2020

Lloyd's Register Foundation

W1529-0076

M.C.

ft. d why

(now ranged)