

1

17 AUG 1922

Sent to Chief Surveyors 15 - 8 - 22

Received from Chief Surveyors

VESSEL'S NAME Ferro Concrete Aux. S. "MOLLIETTE" Report Lon. No. 85175

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.8.92.)

Nature of Survey Annual Survey When due 6.21
Repairs.

The Annual Survey became due 6.21.

Some damage through striking a dock wall requires to be permanently repaired and the vessel examined in dry-dock before proceeding on another voyage under loaded conditions.

The Owner states that after the removal of the Engine last Spring the vessel was taken to the Blackwater where she is now lying and is used as a Houseboat, Etc., and that in the circumstances he understands the class will lapse.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners request.

Ans. H. M.
15-8-22



© 2020

Lloyd's Register
Foundation

WIS49-0002