

DETAIN

10m.11.20.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

25 OCT. 1921

VESSEL'S NAME Wood Sc. "AFTERGLOW". Rpt. Ply. No. 6113

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Plymouth Surveyors report this vessel examined in dry dock owing to reported leakage.

The bottom is stated to have recently been 'coppered' at Southampton but not under the survey of the Society's Surveyors.

3 sheets of metal sheathing have been removed and the seams in way recaulked, the whole of the topside planking recaulked and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed without record of survey 10.21, as recommended.

11 A.1. For fishing purposes.

10.21 Ply.

M. P.
22. 10. 21.

It should be pointed out to the Southampton Surveyors it is understood the bottom of this vessel was recently sheathed by Messrs. Thornycroft at their port, and they should be requested to ascertain the date at which this was done and whether the sheathing is on felt and of copper or yellow metal.



© 2021

Lloyd's Register
Foundation

W1578-0069