

S/c

17

Alan Macwhirter

Chief Surveyors 11.7.18

Received from Chief Surveyors

L'S NAME *Steel Line Steamer*

Report

SL

No. 37927

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

When due

*Letter from the Owners agreeing to the omission of Bulkheads
attaches*

100A-1.

*2 Dks (Steel) Longitudinal framing in double bottom & at checks
fell DB 363 14816. A.P.T. 406*

*FK. One intermediate & 2 lower Dk bulkheads dispensed with,
4 BH to upper Dk. 2 BH to 2nd Dk only.*

Cen. Lugs as per P44 B 454 F 44

Carrying oil fuel F.P. above 150°F in double bottom

M
11.7.18

*The Surveyors should state the number & thickness
of ribs given fitted. This information has been omitted
from the report. fitted*

Lr. 21/8/18



© 2019

Lloyd's Register
Foundation

sets to
s.
Diameter.
Inches.

ribs
"

W158-0064 (1/3)

W158-0062

oved.
Angles.

12.32.6

0.32.6

0.32.6

double

3

3

ed

0

5

5

BEAMS, T.O.P. Deck, Angle, Bulkhead, etc.

Toe Bulb, or Channel

Angles on upper edge

Angle on ditto