

S. S. Lars

Genoa Sept. 30 22

It is submitted that the Surveyor be informed
that in future cases the feed pumps should
not be arranged to pump from the bilges.

S.S.

26. 1. 04



© 2021

Lloyd's Register
Foundation

W1583-0044

Size of compensating ring $4\frac{1}{8} \times \frac{13}{16}$ " plate
No. and Description of Furnaces in each boiler 2 Morrison's Mater