

85279 RB (Trawlers)

10 JUL 1922

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Y. Y. 22
Wood Se. Star Diene

Report

No.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw Shaft

When due

Y. 21

The Examination of the Screw shaft became due in Y. 21.

The Owners Agents at Aberdeen now state that the vessel was dry docked at Peterhead on the 20th May 1921 when a new screw shaft was fitted.

As no notification of this was made to the Surveyors no examination of fitting the new shaft was made.

It is submitted the Aberdeen Surveyors should be requested to arrange with the Owners for the Screw shaft to be examined in place, in order to satisfy themselves that the new shaft was fitted as stated. It to forward a copy of the marks stamped on the shaft to this office. If the examination is satisfactory a fresh notation of NS 5. 21. can be made in the Register Book.

Classing dr
to Hon: 11/7/22

GPR

JWD

8/7/22



© 2021

Lloyd's Register
Foundation