

t. 8.

WRECK

(Received at London Office 22 DEC 1952)

No. 15338.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19 When handed in at Local Office 19 Port of CALCUTTA
 No. in Survey held at CALCUTTA. Date, First Survey and Last Survey 21st November 1952
 Reg. Book. 54644 on the Wood, Iron or Steel. S.S. " CALEDONIA "
 (No. of Visits 1)
 TONNAGE:— Built at NEWCASTLE By whom Swan Hunter & Wigham Richardson Ltd.
 GROSS 5157 Owners A/B CALEDONIA S.S. CO. O/Y Owners' Address
 UNDER DK. 1996 Managers Nils DAHLSTRÖM (If not already recorded in Appendix to Register Book).
 NET 2996 Port belonging to HELSINGFORS.

Surveyed Afloat ~~on the Wood~~ Afloat Name of Dock Esplanade Moorings. Destined Voyage
 WB=Cell D Box D Ba feet; uE&B feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.
 N.B.—All alterations in the existing records should be underlined.
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 2823. Port Cbo.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

CHARACTER. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler surveys (including date of N.B., if any).
+ 100 A1 Spar Deck.		+ LMC 6.50 CL.
7.52 NSW		6.50
SS Shl. 2nd No. 3-12-31 BS 5.52		
SS Rot. 6.50		

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DAMAGE

Damage stated to have been sustained through contact with s.s. " MIZUHO MARU " whilst moored at No.3 Esplanade Moorings, Calcutta on the 12th November, 1952.

Upon Examination found:—

Damage confined to after deck bulwark, port side, abreast mainmast.

Two bulwark plates and gunwale bar in way slightly set in. Four bulwark stanchions slightly bent.

It is recommended permanent repairs be effected at next Special Survey, being considered efficient meantime.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ..								
Removed and Fair'd or Repaired ..								
Fair'd or Repaired in place ..								

PRESENT CONDITION OF THE

Decks ..	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels.
Caulking of Decks	State if Tanks now tested	Double Plates under Sounding Pipes	(State if on Felt.)
Framings	Bulkheads	Engine Room Skylights	When put on, Month Year
Rams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids &c	Boats
Outside Plating	Cement or Asphalt (State which)	Oil Bunkers	Masts, Yards, &c.
in way of sidelights	Rudder	Scuppers	Condition, how ascertained
Weatherhooks	Steering gear and its connections	Cargo Hatchways	(State if wedges removed)
Transoms	Windlass	Hatches	Sails
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Equipment letter
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Anchors, No. of
Longitudinals	Have Water-tight Doors now been examined and found efficient?	Treggalls ditto	Chain Locker
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
Doors		Transoms Pointers & Crutches ditto	Length mean diamr.
Seasons		Timbers of Frame at openings ditto	(on board)
Ringers		Ditto Ditto at other places ditto	Rule length size
Inner Bottom Plating		Stringers, Clamps & Shelves ditto	Hawser & Warps
		Salting ditto	Standing and Running Rigging
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,2,4," or "to remain as classed and to have record of survey, 1,2,4, and the notations of ss. No. 1-24 and ptnd 24, &c."

This vessel is eligible in my opinion to remain as classed, without fresh record of survey subject to permanent repairs to set in bulwark plating etc p.s.a. at next Special Survey.

Survey Fee (Per Section 29) Interim Cert. Rs. 70/-
 Special Damage or Repair Fee (if any) £ :
 (Per Sec. 29)
 Selling Expenses (if chargeable) £ :
 Second Surveyor's Fee (if any) £ :

Fees applied for, 3-12-52
 Received by me, 19

E. Griever
 Surveyor to Lloyd's Register of Shipping.

TUES. 6 JAN 1953

Committee's Minute

Character Assigned

Water 14

THACKER'S PRESS

© 2021

Lloyd's Register Foundation

W1628-0207