

The class is subject to the small pipes from the oil fuel range
the oil burners being renewed in solid drawn steel at the first
rtunity.

5 E

12 NOV 1952

of Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "SHWEDAGON" REPORT Bom. No. 10353.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
so to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
resented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~DAMAGE & WEAR AND TEAR.~~

Vessel examined in dry dock, propeller and outside fastenings
ined.

It is submitted the vessel is eligible to remain as classed, with
~~record-of-survey~~ subject as above as recommended.



© 2021

Lloyd's Register
Foundation

11. 11. 52.

W1629-0137

rs now done

1 stud on sterntube check ring renewed