

# REPORT of SURVEY for REPAIRS, &c.

(Received at London Office)

No 5561

Report 13th Feb 63 When handed in at Local Office 19 Port of AUCKLAND N.Z.  
 Survey held at AUCKLAND N.Z. Date, First Survey 31st January Last Survey 1st February 1953  
 on the ~~Wood Iron or Steel~~ T.W.Sc. S.S. "MAHANA" (No. of Visits Two)

AGE:— Built at BELFAST By whom Workman Clark & Co. Ltd. YEAR 1917 MONTH 7  
 8751 Owners Shaw Savill & Albion Co. Ltd. Owners' Address  
 7889 Managers (if not already recorded in Appendix to Register Book)  
 5263 Port belonging to SOUTHAMPTON

Afloat or in Dry Dock? Afloat Name of Dock Destined Voyage U.K.  
 DBa feet; uE&B feet; f feet }  
 Capacity tons; FPT tons; APT tons; MT tons }  
 Alterations in the existing records of tanks should be inserted.  
 All Alterations in the existing records should be underlined.

Report, No. 136539 Port Lw

Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to be surveyed should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of repairs. Repairs on account of Damage (the cause of which must be stated) separated from Repairs due to other causes; and besides being detailed in the body of the report, should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters received in this case).

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys	Machinery and Boiler Surveys (including date of N.B., if any)
+100A1 shelter	+LMC 12.48
deck with free-	ISCL S 7.51
board 12.52	P 6.49
SSLiv. 12.48 (RR)	BS 7.51
	12.52

Where the Surveyor has not made a special damage report he is required to state whether he offered for this purpose and to whom and why they were declined.  
 Was a damage report made by anyone else? If so, by whom?  
 Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins. Ref. Mch

## EXAMINATION AS PER RULE, FOR REPAIRS.

E:- Wasted and holed section of double bottom tank filling pipe renewed in No. 4 lower port side aft. Tank pressed up to full height on completion and repair found tight.

DAMAGE REPAIRS:—	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Beams	Inner Bottom Plates	Dk. Plates	Other Items:—
and Fair'd or Repaired								
Repaired in place								

Bulkheads Ceiling Cement or Asphalt Rudder Steering gear and its connections Windlass Have pumps been examined and found efficient? Have Sluice Valves been examined and found efficient? Have Watertight Doors been examined and found efficient? Have Ventilators and their Coamings been examined and found efficient? Air and Sounding Pipes Doubling Plates under Sounding Pipes	Engine Room Skylights Coal Bunkers, Openings, Covers, &c. Oil Bunkers Souppers Cargo Hatchways Hatches Planking Caulking Treennails Breasthooks & Stemson Transoms, Pointers & Crutches Timbers of Frame at openings " " at other places Stringers, Clamps & Shelves Salting (State if examined)	Copper, or Y.M. (State if on Felt) When fitted: Month Year Boats Masts, Yards, &c. Condition, how ascertained (State if wedges removed) Equipment letter Anchors, No. of Cables (State if now ranged) " length mean diamr. (on board) " Rule length size Chain Locker Hawser & Warps Standing and Running Rigging Sails
--	---	---

Observations, Opinion as to Class, Recommendation, &c.:—  
 clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent survey, thus, for example:—  
 "133," or "to remain as classed and to have record of survey, 138, and the notations of ss No. 138."  
 as now seen, is eligible in my opinion to remain as classed without fresh record  
 vey, subject to all conditions at present attached to vessel's class as previously  
 ended.

Repair Fee (if any)	5	5	-
(if chargeable)			
Fee (if any)			

Fees applied for, 13/2/1953


Received by me, 19

Minute THU 5 MAR 1953

Surveyor to Lloyd's Register of Shipping

Character Assigned

Deferred for comb SS



W1633-0177