

69112

4 MAR 1953 E

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

"MAHANA"

REPORT Auk. No. 5561

The Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD.

due 12,52 , partly held 12,52

the further advanced and the following repairs effected (due to

HTUOS To

475292

I will

to 79

menhmen

beirwo

minim

is submitted that this proposal merits approval and the vessel is
e to remain as classed, and WILL BE eligible for the record

12,52 when the survey has been completed (with endorsement)

following remains to be done to complete the Survey

1 Rule requirements except examination of:-

Starboard HP turbine,
Port LP turbine,
Starboard thrust shaft,
Starboard feed pump
Weirs and starboard independent air pumps,
Port circulating pump,
Starboard lubricating oil pump,
Starboard fan engine,
Windlass and steering gear engines.



2021
3.3.53.

Lloyd's Register
Foundation