

Received from Chief Ship Surveyor

30 MAR 1953

NAME

MAHIA

REPORT

Wellington

No. N.Z.

Existing Conditions of Class: Subject to indented shell plate N°5 (p.s.) in 4" stroke below sheer, side bunkers, side bunkers and buckled earnings (p.s.), pitted shell plating (p.s.) in way of fore peak tank, N°1 D.B. tank, N°1 hold, and in way of scuppers being examined and dealt with by completion of the S.S., to 15 fms. of chain cable being renewed at the earliest opportunity, and to bolts in breast hook angle in space above fore peak being replaced by rivets by completion of the S.S.

Requirement of Class (B) (As before or None)

Special Survey (C) due 2.53, commenced Gls. 11.52.

of Present Survey: (Afloat and in dry dock)

Temporary repairs to damage caused by falling cargo.

1 Features:

Permit Certificate in order (Yes No None)

Outstanding: (If any for S.S. or A.S.)

For portion of survey held see Gls. report 79638

to be completed by:

Recommendation: Subject as above, and to permanent repairs to set down shelter deck abreast N°2 hatch (s.s.) on ship's return to U.K. from her present voyage, but FURTHER ACTION be DEFERRED for completion of the Special Survey.

As now. Subject

EK
28.3.53

© 2021

S.S. Partly Held

Lloyd's Register
Foundation