

No. of Donkey Boilers  
Steam Pressure—  
in Main Boilers

200 lb.

If Surveyed Afloat or in Dry Dock Afloat. St. Andrew's Dock  
(State name of Dock.)

Particulars of Classification  
precisely as in Register

CHARACTER

4 E

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME

"SWANLAND"

REPORT Hul.

No. 59993.

-9 FEB 1954

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Result of Survey

REPAIRS TO ~~ENGINE AND BOILERS~~ ~~DUE TO DAMAGE THROUGH~~

Main boiler centre furnace jacked.

The two top Central longitudinal steam space stays were found somewhat wasted and recommended for renewal.

The Surveyor recommends that the centre furnace be re-examined and the two longitudinal steam space stays be renewed before the end of 4,54

It is submitted that the vessel will be eligible for the second BS 1,54 when the centre furnace has been re-examined and the two longitudinal steam space stays renewed, and in no case later than the end of 4,54.

*HL*

5.2.54



© 2020

Lloyd's Register  
Foundation

Survey Fee (per Section 23)

B.S.

25 : 0 0

Fee applied for  
28 JAN 1954

Special Damage or Repair Fee (if any)