

RECEIVED

(if assigned) as  
and now verified

U.W.

19. NOV 1953

WRECK  
SECTION

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

No. 1  
"AINA MARIA NURMINEN"

REPORT

Kel. No. 947

JD.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

This ship has sustained extensive damage caused by mine explosion on 18.7.53 when on a voyage in loaded condition.


The KIEL Surveyors report (9,53) ship examined afloat and in drydock and necessary recommendations made, should it be decided to retain the ship in service.

The Owners state in a letter dated 17.10.53 that the ship is to be disposed of as scrap.

IT IS ACCORDINGLY SUBMITTED ACTION be DEFERRED pending further information regarding ultimate disposal of this ship.

R.S.P

13.11.53



© 2020

Lloyd's Register  
Foundation

W1642-0075

Finland.

owed i  
damage  
ship wh  
the v

l ceil  
tanks  
steeri

ems:—

Y.M.....  
(on Felt.)  
d, Month

rds, &c.  
how asc  
f wedges  
t letter...  
No. of ...  
ate if now

yth  
(in bec  
e length  
ker.....  
Warps.  
nd Runn