

8 DEC 1953

Received from Chief Ship Surveyor

SHIP'S NAME "AKENSIDE"

REPORT

Nwc.

No. 110922

WRECK SECTION

WRECK SECTION

Outstanding Conditions of Class:

to R.Q. deck, sheer plate (p.s.f.) etc., to indented shell plating etc. (p.s.f.) and to indented B.4 etc (p.s.f.) being dealt with by the Special Survey. Subject to permanent repairs

ACTION is DEFERRED for examination in dry dock after grounding.

Endorsement of Class (B) (~~As before~~ None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to contact damage.


Recommendation:

SUBJECT as above, also to permanent repairs to shell and slightly buckled bulkhead aft end No.2 hold (p.s.) (cement box) next drydocking, but further ACTION continue to be DEFERRED for examination in dry dock after grounding.

As Now. Subject.

INS R.L.

Drydocking (grounding).



© 2000
R.S.P.
7.12.53

Lloyd's Register
Foundation

W1642 - 0306