

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 18th Jan. 1954

When handed in at Local Office 19

Port of Suez

No. in
Reg. Book.

Survey held at Suez

Date, First Survey 6th January Last Survey 12th January 1954

(No. of Visits 5)

09719

on the Wood, Iron or Steel Twin Sc. M.V. FAUNUS

TONNAGE

GROSS 3800

UNDER DK 3339

NET 2706

Built at Dundee

By whom Caledon S.B. & Co. Ltd.

When 1914

MONTH

Owners Anglo-Saxon Petroleum Co. Ltd.

Owners' Address

Managers -ditto-

(If not already recorded in Appendix to Register Book)

Port belonging to London

Surveyed Afloat or in Dry Dock? both Name of Dock K. M. L. Drydock.

Destined Voyage

Cell DBor DBa feet; uE & B. feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 5183 Port P. od.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and Items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } OIL ENGINES

Was a damage report made by anyone else? if so, by whom? CONTINUOUS SURVEY

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking, general examination and issue of Interim Certificate for towage to United Kingdom.

Now done for Docking:- Shell plating stern, frame and rudder cleaned examined and found in satisfactory condition. Last seen in drydock 8/1/54.

Decks, casings, hatchways, hatches, ventilators, coamings and their closing appliances examined and found or placed in satisfactory condition.

A number of cargo tanks, the pump room, forward hold, peaks and machinery spaces generally examined internally and found satisfactory. Windlass and steering gear examined and found in order.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plating	Frames	R. Frames	Floors and Bracket Floors	Beams	Inner Bottom Plates	Dk. Plates	Other Items :-
Renewed ...								
Removed and Paired or Repaired								
Paired or Repaired in place ...								

PRESENT CONDITION OF THE parts now seen:-

Decks satisfactory	Bulkheads satisfactory	Engine Room Skylights satisfactory	Copper, or Y.M. (State if on felt.)
Caulking of Decks -	Ceiling -	Coal Bunkers, Openings, Covers, &c. -	When fitted, Month Year
Coamings satisfactory	Cement or Asphalt -	Oil Bunkers -	Boats Good
Beams & Fastenings "	Rudder Good	Scuppers Good	Masts, Yards, &c. -
Outside Plating "	Steering gear and its connections Good	Cargo Hatchways Good	Condition, how ascertained -
" " in way of sidelights "	Windlass Good	Hatches Good	(State if wedges removed.)
Frames "	Have pumps been examined and found efficient? -	Planking -	Equipment letter
Reverse Frames "	Have Stillee Valves been examined and found efficient? -	Caulking -	Anchors, No. of 3b 1k 1s.
Longitudinals "	Have Watertight Doors been examined and found efficient? -	Treenails -	Cables (State if now ranged) No stated complete
Transverses "	Have Ventilators and their Coamings been examined and found efficient? Yes	Breasthooks & Stemson -	" length (on board.) mean diam.
Floors -	Have Sounding Pipes -	Transoms, Pointers & Crutches -	" Rule length size
Keelsons -	Doubling Plates under Sounding Pipes -	Timbers of Frame at openings -	Chain Locker -
Stringers -		" " at other places -	Hawsers & Warps sufficient
Inner Bottom Plating -		Stringers, Clamps & Shelves -	Standing and Running Rigging -
Have the Tanks been examined internally? Partly		Salting -	Sails -
Have the Tanks been tested? No		State if examined	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Considered fit in our opinion to be towed to the United Kingdom.

Survey Fee (per Section 23)	£ E. : 30. 000	Fees applied for, 16/1/ 19 54
Special Damage or Repair Fee (if any) (per Sec. 23)	£ : :	Received by me, 19
Travelling Expenses (if chargeable)	£ : 5. 750	
Special Att. fee	4. 000	
Second Surveyor's Fee (if any) (J. de Wolf)	: 15. 000	

Committee's Minute

Character Assigned

Deferred await further information

TUESDAY 16 FEB 1954

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

W1644-6083

Interim Certificate issued copy attached.

Lloyd's Register
Foundation