

16 SEP 1953

SHIP NAME

BECKENHAM

REPORT

Nwc.

No.

110690

Standing Conditions of Class:

Subject to top of stern frame (E.W. and reinforced 12.51 and E.W. 3.48) being specially, also to indented shell plating etc (p.s.a.) being dealt with next dry-docking, but ACTION is DEFERRED for examination in dry-dock, after grounding

Assessment of Class (B) (~~As before or~~ None)

Place of Present Survey: (Afloat and in dry dock)

Docking: Examination in dry-dock, after grounding (no damage)
Permanent repairs to indented shell plating etc (p.s.a.) as above.

Recommendation:

Submitted the record of docking 8.53. Rec assigned,
Subject to top of stern frame (E.W. + reinforced 12.51 and E.W. 3.48) being specially examined next dry-docking, without other conditions

8.53 Shl. subject
without

Delete from S.R.L.

Dry-docking (grounding)



© 2020

Lloyd's Register
Foundation

W1644-0154