

W1646-0089

Received from Chief Surveyors _____

Chief Surveyors _____

EL'S NAME STEEL S.S. "COLON"

Report LIX. No. 79652

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

of Survey _____ When due _____

The Downton Pump has been dispensed with for the present, but it is included
Owners are agreeable to fit same when requested.

* 100 A.1. (steel) "Shelter Dk with freeboard"

1 Dk. (steel) and Shelter Dk (steel)

Cell DB 224' A085. FPT 635. APT 185.

FK. Collision BH to Shelter Dk 3 BH to upper Dk. Conn.

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

The Surveyor should be requested to forward the usual

Lloyd's Register Foundation

2020

M

atb

18-10-19

Ships Engine & Castings reports.

LIX-206/119