

W1646-0217

2 E

26 MAY 1952

for Surveyor

Received from Chief Engineer Surveyor

'CASANDRA'

REPORT

Geo.

No. 3868

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and
out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

SECTION OF SPECIAL SURVEY OF ENGINES AND BOILERS

Survey, due 3.52 now held
partly

TROW

~~and the following repairs carried out (due to~~

):-

Some edge cracks in both boilers made good by welding and a
ets renewed. A stay tube renewed in the starboard boiler.

is submitted the vessel is eligible to remain as classed, with
of BS 3.52.

as recommended.

© 2020

Lloyd's Register
Foundation

23. 5. 52.