

27 JAN 1951 4E

Received from Chief Engineer Surveyor

SHIP'S NAME

"INCHMAY"

REPORT

H.Kg.

No.11802

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

REMARKS OF SURVEYOR REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH HEAVY WEATHER.

Main engine bilge pumps and the general service pump opened out, examined and placed in order. A steam pipe to the windlass renewed. Electric circuits at the forward end of the vessel placed in order.

Wear and tear repairs The stern gland repacked and the condenser and some pumps placed in order.

IT IS SUBMITTED the vessel is eligible to remain as classed.



Lloyd's Register  
Foundation

26.1.54

W1649-0009