

(Received at London Office)

Committee's Minute.....
Assigned

TUESDAY 15 SEP 1953
As met
Bkr. 5.7.53 subject

Acting Surveyor to Lloyd's Register
Lloyd's
W1649-0251

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

W1649-0251

Docking Survey.

Now done:

The vessel was placed in the Government Graving Dock.

The propeller and sea connections and fastenings were examined and found in good condition.

The steering engine and windlass were examined without opening out, seen under working conditions and found in order.

Boiler Survey.

Now done:

The port, centre and starboard boilers were examined internally and externally with mountings and the safety valves adjusted under steam.

Repairs now effected:

Centre Boiler.

5 leaking plain tubes stoppered.



© 2021

Lloyd's Register
Foundation