

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office SEP 20 1938)

Date of writing Report 17/9/1938 When handed in at Local Office 17/9/1938 Port of NEWCASTLE-ON-TYNE

No. in Reg. Book 88205 Survey held at Newcastle-on-Tyne Date, First Survey and Last Survey 15/9/1938 (No. of Visits 1)

on the Machinery of the Wood, Iron or Steel S/S GRAYBURN. Tonnage Gross 6035 Net 3570 Vessel built at Sunderland By whom J. Long & Co. Ltd. When 1938 Engines made at Sunderland By whom G. Clark (1938) Ltd. When 1938 Boilers, when made (Main) 1938 (Donkey) Owners Waller & Co. Ltd. Owners' Address Managers Port London Voyage If Surveyed Afloat or in Dry Dock Dry dock. (State name of Dock.) Hawthorn Leslie & Co. Newcastle.

Last Report No. Port

Particulars of Examination and Repairs (if any) Docking.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Did the Surveyor personally go inside each Donkey Boiler separately and make a thorough examination at this time?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. Close.

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms.?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Vessel in dry dock, propellers and outside fastenings examined and found in good order.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, E.S. 9,11, E.&M.S. 9,11, L.M.C. 9,11, or L.M.C. 140 lb., F.D., &c.)


This Report is written for the information of the Committee.

Survey Fee (per Section 29) £ : Fees applied for 19
Special Damage or Repair Fee (if any) (per Section 29.) £ : Received by me, 19
Travelling expenses (if chargeable) £ : :

A. Pemberton
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute FRI 30 SEP 1938

Assigned Su Sld. 32480



Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to