

20 NOV 1939

Hai Kwang.

Shi 4563.

It is submitted the attached reports
be sent to the London office in
order to establish whether the old
straight shafting which has been retained
is suitable for the new engine, also to
check the size of the crank shaft
of the new engine.

condition of shafts
examined

20/11/39

Found Satisfactory.

[Signature]

W. H.
21.11.39

[Signature]

Lloyd's Register
Foundation

W177-0130